

Multimodal Access Opportunity Scores

This score is based on the physical assets and barriers that determine each school or site's potential for increased walking, bicycling, carpooling and bus/transit use. Current travel modes (how people are accessing the school now) are not a factor in the score.



Contact information:

Taylor Elementary School 2600 N Stuart St. Arlington, VA 22207 Phone: 703.228.6275

Type of Site:

Elementary School

Grade Levels:

K - 5

Summary Conditions

Taylor Elementary School is in northwest Arlington County, adjacent to Potomac Overlook Park. This school is located east of Military Road and north of Lee Highway/Route 29. In 2013, Taylor Elementary School had 744 students and 97 staff members.

Neighborhood Context

Taylor Elementary School is surrounded by single-family, detached residential development. There appears to be a relatively low traffic volumes on surrounding streets, including North Stuart Street. The majority of streets have sidewalks on one side of the street. Some streets do not allow for street parking due to narrow street width. The neighborhood around Taylor is relatively hilly and many of the nearby streets have steep elevations.

Transportation Assets

Taylor Elementary School has access to bus transit within two blocks of the campus. There are no Metro or Capital Bikeshare stations nearby. There are bike racks at the front entrance of the school. Military Road, which is east of the campus, has bicycle lanes.

On the north side of campus there is a steep concrete path that begins at Military Road and connects to the north side of campus. This path begins along the perimeter of the residential parcels north of the school and continues through the wooded area. There are also dirt paths that have been created to allow for a shorter distance to the school from a daycare center north of the school on Military Road. There is a sign as you enter the path from the school that informs you where it leads. This dirt path also acts as an emergency evacuation route for Taylor Elementary School.

Physical Barriers

A major barrier around Taylor Elementary School is the slope to the west of campus. This slope is between the school and the trail system to the west. Steep slopes also create some connectivity issues in the area around the school.

Existing Travel Modes (from 2013 School Surveys)

